APPENDIX 6E: INDOOR QUALITY AUDIT - CHURCH STRETTON POOL AND SPORTS CENTRE

Name of facility

Church Stretton Pool and Sports Centre

Address

SY6 6ER

QUALITY RATING

General Condition	Excellent		Good	х	Average		Poor	Very Poor	
Need for capital investmer	Minimal		Moderate		Significant	Х			
Facility Quality	-				-		-		
4 court hall	Excellent	Х	Good		Average		Poor	Very Poor	
20m x 4 laneLearner Pool	Excellent		Good		Average		Poor	Very Poor	Х
16 station fitness suite	Excellent	Χ	Good		Average		Poor	Very Poor	
Studio	Excellent	Χ	Good		Average		Poor	Very Poor	
Reception	Excellent		Good		Average	Х	Poor	Very Poor	
Changing Rooms	Excellent		Good	Х	Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
	Excellent		Good		Average		Poor	Very Poor	
									6
Disability Access	Full	Х	Partial		No		1		

Disability Access	Full	Х	Partial		No		
Served by Public Transpor	Yes	Х	No			-	
Good Natural Presence	Excellent		Good	Х	Average	Poor	
Well Signposted	Good	Х	Some		Poor		
Car Parking	Good	Х	Some		Poor		
Development Potential	Lots		Some	Х	No potential		

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

Built 2012

Pool is in very poor condition compared to rest of facility

72%